


25 METER ZEROING TARGET M4 CARBINE

CALIBRATED FOR A 300M ZERO



ZERO TARGET DATA FOR M4 CARBINE

- 1- ROTATE REAR SIGHT ELEVATION KNOB TO THE 8/3 SETTING FOR ZEROING AT 25 METERS.
- 2- AIM AT TARGET CENTER. ADJUST SIGHTS TO MOVE SHOT GROUP CENTER AS CLOSE AS POSSIBLE TO THE WHITE DOT IN THE CENTER OF TARGET.
- 3- AFTER COMPLETION OF THE 25 METER ZERO THE WEAPON WILL BE ZEROED FOR 300 METERS.